




**CLIENT :**

**Fiche  
Technique  
CR 73**

## CRAMPILLON



Date	Indice	Objet
26/03/07	A	Création
14/01/08	B	Ajout 4x30
07/03/08	C	Ajout 4 x 35
23/06/09	D	Ajout cote E
16/07/10	E	Ajout 4.5x45

**Visa :**

**Conditionnement : 1 kg - 5 kg - Seaux**

**Revêtement : Clair – Galva – EZN**

**Tonnage :**

**Machine N°**

Désignation	d	C	L	E max	Code 5kg	
<b>2,70 x 27</b>	<b>2.65 / 2.75</b>	<b>5,50</b>	<b>27 ± 1</b>	<b>14</b>		
<b>3,00 x 30</b>	<b>3,00 / 3,10</b>	<b>6,00</b>	<b>30 ± 1</b>	<b>15,5</b>		
<b>3,50 x 35</b>	<b>3,48 / 3,55</b>	<b>7,00</b>	<b>35 ± 1</b>	<b>17,5</b>		
<b>4,00 x 30</b>	<b>3,95 / 4,05</b>	<b>9,00</b>	<b>30 ± 1</b>	<b>19</b>		
<b>4,00 x 35</b>	<b>3,95 / 4,05</b>	<b>9,00</b>	<b>35 ± 1</b>	<b>19</b>	<b>304527</b>	
<b>4,50 x 40</b>	<b>4,48 / 4,55</b>	<b>10,00</b>	<b>40 ± 1</b>	<b>22</b>		
<b>4,50 x 45</b>	<b>4,48 / 4,55</b>	<b>10,00</b>	<b>45 ± 1</b>	<b>22</b>		
<b>5,00 x 50</b>	<b>4,98 / 5,12</b>	<b>10,00</b>	<b>50 ± 1</b>			